

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									<b>10</b>	Air Quality Levels	Site Specific Trigger Levels	
<b>Target Air Quality Levels</b>									<b>10</b>			
<b>EPA Site Specific Trigger Levels</b>												
SILICA-ST1-3/8/06	040604471-0001	Southwest Area (sidewalk bridge level)	3/8/06	3.51	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST2-3/8/06	040604471-0002	Southeast Area (sidewalk bridge level)	3/8/06	3.51	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST4-3/8/06	040604471-0003	Northwest Area (street-level)	3/8/06	3.56	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST5-3/8/06	040604471-0004	Firehouse #10 (roof level)	3/8/06	3.57	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST10-3/8/06	040604471-0005	North Side Sidewalk Bridge	3/8/06	3.55	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST11-3/8/06	040604471-0006	90 Trinity Place (roof level)	3/8/06	3.56	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST12-3/8/06	040604471-0007	110 Greenwich Street (roof level)	3/8/06	3.56	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST13-3/8/06	040604471-0008	Marriott Hotel, 38th Floor (roof level)	3/8/06	3.51	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST14-3/8/06	040604471-0009	West Face - South end at corner (scaffolding level)	3/8/06	3.6	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST15-3/8/06	040604471-0010	South Face - East end at corner (scaffolding level)	3/8/06	3.59	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST16-3/8/06	040604471-0011	East Face - North end at corner (scaffolding level)	3/8/06	3.56	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST17-3/8/06	040604471-0012	North Face - West end at corner (scaffolding level)	3/8/06	3.6	Silica	NIOSH 7500 XRD	EMSL	3/10/06	< 1	No	No	
SILICA-ST1-3/9/06	040604557-0001	Southwest Area (sidewalk bridge level)	3/9/06	3.59	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST2-3/9/06	040604557-0002	Southeast Area (sidewalk bridge level)	3/9/06	3.58	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST4-3/9/06	040604557-0003	Northwest Area (street-level)	3/9/06	3.57	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST5-3/9/06	040604557-0004	Firehouse #10 (roof level)	3/9/06	3.58	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST10-3/9/06	040604557-0005	North Side Sidewalk Bridge	3/9/06	3.54	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST100-3/9/06	040604557-0013	Station 10 Field Duplicate	3/9/06	3.53	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST11-3/9/06	040604557-0006	90 Trinity Place (roof level)	3/9/06	3.59	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST12-3/9/06	040604557-0007	110 Greenwich Street (roof level)	3/9/06	3.6	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST13-3/9/06	040604557-0008	Marriott Hotel, 38th Floor (roof level)	3/9/06	3.55	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST14-3/9/06	040604557-0009	West Face - South end at corner (scaffolding level)	3/9/06	3.59	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST15-3/9/06	040604557-0010	South Face - East end at corner (scaffolding level)	3/9/06	3.58	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST16-3/9/06	040604557-0011	East Face - North end at corner (scaffolding level)	3/9/06	3.58	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	
SILICA-ST17-3/9/06	040604557-0012	North Face - West end at corner (scaffolding level)	3/9/06	3.58	Silica	NIOSH 7500 XRD	EMSL	3/11/06	< 1	No	No	