

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-3/19/08	040806613-0001	Southwest Area (sidewalk bridge level)	3/19/08	3.61	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST2-3/19/08	040806613-0002	Southeast Area (sidewalk bridge level)	3/19/08	3.73	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST4-3/19/08	040806613-0003	Northwest Area (street-level)	3/19/08	3.73	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST5-3/19/08	040806613-0004	Firehouse #10 (roof level)	3/19/08	3.53	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST10-3/19/08	040806613-0005	North Side Sidewalk Bridge	3/19/08	3.85	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST11-3/19/08	040806613-0006	90 Trinity Place (roof level)	3/19/08	3.63	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST12-3/19/08	040806613-0007	110 Greenwich Street (roof level)	3/19/08	3.66	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST13-3/19/08	040806613-0008	Marriott Hotel, 38th Floor (roof level)	3/19/08	3.6	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST14(15th) -3/19/08	040806613-0009	West Face - South end at corner (scaffolding level: 15th floor)	3/19/08	3.52	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST15(15th) -3/19/08	040806613-0010	South Face - East end at corner (scaffolding level: 15th floor)	3/19/08	3.59	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST16(15th) -3/19/08	040806613-0011	East Face - North end at corner (scaffolding level: 15th floor)	3/19/08	3.52	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST17(15th) -3/19/08	040806613-0012	North Face - West end at corner (scaffolding level: 15th floor)	3/19/08	3.7	Silica	NIOSH 7500 XRD	EMSL	3/20/08	< 1	No	No	
SILICA-ST1-3/20/08	040806737-0001	Southwest Area (sidewalk bridge level)	3/20/08	3.56	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	
SILICA-ST2-3/20/08	040806737-0002	Southeast Area (sidewalk bridge level)	3/20/08	3.63	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	
SILICA-ST4-3/20/08	040806737-0003	Northwest Area (street-level)	3/20/08	3.45	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	
SILICA-ST5-3/20/08	040806737-0004	Firehouse #10 (roof level)	3/20/08	3.58	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	
SILICA-ST10-3/20/08	040806737-0005	North Side Sidewalk Bridge	3/20/08	3.65	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	
SILICA-ST100-3/20/08	040806737-0012	Station 10 Field Duplicate	3/20/08	3.6	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	
SILICA-ST11-3/20/08	040806737-0006	90 Trinity Place (roof level)	3/20/08	3.54	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	
SILICA-ST12-3/20/08	040806737-0007	110 Greenwich Street (roof level)	3/20/08	3.54	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	
SILICA-ST14(15th) -3/20/08	040806737-0008	West Face - South end at corner (scaffolding level: 15th floor)	3/20/08	3.63	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	
SILICA-ST15(15th) -3/20/08	040806737-0009	South Face - East end at corner (scaffolding level: 15th floor)	3/20/08	3.61	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	
SILICA-ST16(15th) -3/20/08	040806737-0010	East Face - North end at corner (scaffolding level: 15th floor)	3/20/08	3.58	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	
SILICA-ST17(15th) -3/20/08	040806737-0011	North Face - West end at corner (scaffolding level: 15th floor)	3/20/08	3.62	Silica	NIOSH 7500 XRD	EMSL	3/21/08	< 1	No	No	

Note:

1. The silica sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on March 20, 2008 was not available for analysis on account of sample damage.