

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
EPA Site Specific Trigger Levels									10			
SILICA-ST1-4/25/08	040809960-0001	Southwest Area (sidewalk bridge level)	4/25/08	3.57	Silica	NIOSH 7500 XRD	EMSL	4/26/08	2	No	No	
SILICA-ST2-4/25/08	040809960-0002	Southeast Area (sidewalk bridge level)	4/25/08	3.55	Silica	NIOSH 7500 XRD	EMSL	4/26/08	< 1	No	No	
SILICA-ST4-4/25/08	040809960-0003	Northwest Area (street-level)	4/25/08	3.56	Silica	NIOSH 7500 XRD	EMSL	4/26/08	2	No	No	
SILICA-ST5-4/25/08	040809960-0004	Firehouse #10 (roof level)	4/25/08	3.58	Silica	NIOSH 7500 XRD	EMSL	4/26/08	1	No	No	
SILICA-ST10-4/25/08	040809960-0005	North Side Sidewalk Bridge	4/25/08	3.29	Silica	NIOSH 7500 XRD	EMSL	4/26/08	2	No	No	
SILICA-ST11-4/25/08	040809960-0006	90 Trinity Place (roof level)	4/25/08	3.56	Silica	NIOSH 7500 XRD	EMSL	4/26/08	1	No	No	
SILICA-ST12-4/25/08	040809960-0007	110 Greenwich Street (roof level)	4/25/08	3.54	Silica	NIOSH 7500 XRD	EMSL	4/26/08	< 1	No	No	
SILICA-ST13-4/25/08	040809960-0008	Marriott Hotel, 38th Floor (roof level)	4/25/08	3.54	Silica	NIOSH 7500 XRD	EMSL	4/26/08	< 1	No	No	
SILICA-ST14(15th) -4/25/08	040809960-0009	West Face - South end at corner (scaffolding level: 15th floor)	4/25/08	3.38	Silica	NIOSH 7500 XRD	EMSL	4/26/08	< 1	No	No	
SILICA-ST15(15th) -4/25/08	040809960-0010	South Face - East end at corner (scaffolding level: 15th floor)	4/25/08	3.35	Silica	NIOSH 7500 XRD	EMSL	4/26/08	< 1	No	No	
SILICA-ST16(15th) -4/25/08	040809960-0011	East Face - North end at corner (scaffolding level: 15th floor)	4/25/08	3.51	Silica	NIOSH 7500 XRD	EMSL	4/26/08	< 1	No	No	
SILICA-ST17(15th) -4/25/08	040809960-0012	North Face - West end at corner (scaffolding level: 15th floor)	4/25/08	3.34	Silica	NIOSH 7500 XRD	EMSL	4/26/08	< 1	No	No	