

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-5/21/06	0406010048-0001	Southwest Area (sidewalk bridge level)	5/21/06	3.64	Silica	NIOSH 7500 XRD	EMSL	5/22/06	< 1	No	No	
SILICA-ST2-5/21/06	0406010048-0002	Southeast Area (sidewalk bridge level)	5/21/06	3.65	Silica	NIOSH 7500 XRD	EMSL	5/22/06	< 1	No	No	
SILICA-ST4-5/21/06	0406010048-0003	Northwest Area (street-level)	5/21/06	3.73	Silica	NIOSH 7500 XRD	EMSL	5/22/06	< 1	No	No	
SILICA-ST5-5/21/06	0406010048-0004	Firehouse #10 (roof level)	5/21/06	3.57	Silica	NIOSH 7500 XRD	EMSL	5/22/06	< 1	No	No	
SILICA-ST10-5/21/06	0406010048-0005	North Side Sidewalk Bridge	5/21/06	3.65	Silica	NIOSH 7500 XRD	EMSL	5/22/06	< 1	No	No	
SILICA-ST11-5/21/06	0406010048-0006	90 Trinity Place (roof level)	5/21/06	3.45	Silica	NIOSH 7500 XRD	EMSL	5/22/06	< 1	No	No	
SILICA-ST12-5/21/06	0406010048-0007	110 Greenwich Street (roof level)	5/21/06	3.61	Silica	NIOSH 7500 XRD	EMSL	5/22/06	< 1	No	No	
SILICA-ST14-5/21/06	0406010048-0008	West Face - South end at corner (scaffolding level)	5/21/06	3.74	Silica	NIOSH 7500 XRD	EMSL	5/22/06	< 1	No	No	
SILICA-ST15-5/21/06	0406010048-0009	South Face - East end at corner (scaffolding level)	5/21/06	3.75	Silica	NIOSH 7500 XRD	EMSL	5/22/06	< 1	No	No	
SILICA-ST16-5/21/06	0406010048-0010	East Face - North end at corner (scaffolding level)	5/21/06	3.73	Silica	NIOSH 7500 XRD	EMSL	5/22/06	< 1	No	No	
SILICA-ST17-5/21/06	0406010048-0011	North Face - West end at corner (scaffolding level)	5/21/06	3.77	Silica	NIOSH 7500 XRD	EMSL	5/22/06	< 1	No	No	
SILICA-ST1-5/22/06	040610184-0001	Southwest Area (sidewalk bridge level)	5/22/06	3.52	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 1	No	No	
SILICA-ST2-5/22/06	040610184-0002	Southeast Area (sidewalk bridge level)	5/22/06	3.52	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 1	No	No	
SILICA-ST4-5/22/06	040610184-0003	Northwest Area (street-level)	5/22/06	3.43	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 1	No	No	
SILICA-ST5-5/22/06	040610184-0004	Firehouse #10 (roof level)	5/22/06	3.61	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 1	No	No	
SILICA-ST10-5/22/06	040610184-0005	North Side Sidewalk Bridge	5/22/06	3.46	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 6	No	No	
SILICA-ST11-5/22/06	040610184-0006	90 Trinity Place (roof level)	5/22/06	3.63	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 1	No	No	
SILICA-ST12-5/22/06	040610184-0007	110 Greenwich Street (roof level)	5/22/06	3.65	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 1	No	No	
SILICA-ST13-5/22/06	040610184-0008	Marriott Hotel, 38th Floor (roof level)	5/22/06	3.64	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 1	No	No	
SILICA-ST14-5/22/06	040610184-0009	West Face - South end at corner (scaffolding level)	5/22/06	3.63	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 1	No	No	
SILICA-ST15-5/22/06	040610184-0010	South Face - East end at corner (scaffolding level)	5/22/06	3.62	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 1	No	No	
SILICA-ST16-5/22/06	040610184-0011	East Face - North end at corner (scaffolding level)	5/22/06	3.62	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 1	No	No	
SILICA-ST17-5/22/06	040610184-0012	North Face - West end at corner (scaffolding level)	5/22/06	3.6	Silica	NIOSH 7500 XRD	EMSL	5/23/06	< 1	No	No	

Note:

1. Silica sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on May 21, 2006 was not available for analysis on account of pump failure.