

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									<b>10</b>	Air Quality Levels	Site Specific Trigger Levels	
									<b>10</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>												
SILICA-ST1-6/3/09	040914005-0001	Southwest Area (sidewalk bridge level)	6/3/09	3.78	Silica	NIOSH 7500 XRD	EMSL	6/4/09	< 1	No	No	
SILICA-ST2-6/3/09	040914005-0002	Southeast Area (sidewalk bridge level)	6/3/09	3.65	Silica	NIOSH 7500 XRD	EMSL	6/4/09	< 1	No	No	
SILICA-ST4-6/3/09	040914005-0003	Northwest Area (street-level)	6/3/09	3.61	Silica	NIOSH 7500 XRD	EMSL	6/4/09	4	No	No	
SILICA-ST5-6/3/09	040914005-0004	Firehouse #10 (roof level)	6/3/09	3.87	Silica	NIOSH 7500 XRD	EMSL	6/4/09	6	No	No	
SILICA-ST10-6/3/09	040914005-0005	North Side Sidewalk Bridge	6/3/09	3.58	Silica	NIOSH 7500 XRD	EMSL	6/4/09	< 1	No	No	
SILICA-ST11-6/3/09	040914005-0006	90 Trinity Place (roof level)	6/3/09	3.66	Silica	NIOSH 7500 XRD	EMSL	6/4/09	< 1	No	No	
SILICA-ST12-6/3/09	040914005-0007	110 Greenwich Street (roof level)	6/3/09	3.54	Silica	NIOSH 7500 XRD	EMSL	6/4/09	< 1	No	No	
SILICA-ST13-6/3/09	040914005-0008	Marriott Hotel, 38th Floor (roof level)	6/3/09	3.6	Silica	NIOSH 7500 XRD	EMSL	6/4/09	< 1	No	No	