

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
									10			
SILICA-ST1-6/20/08	040815273-0001	Southwest Area (sidewalk bridge level)	6/20/08	3.59	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	
SILICA-ST2-6/20/08	040815273-0002	Southeast Area (sidewalk bridge level)	6/20/08	3.74	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	
SILICA-ST4-6/20/08	040815273-0003	Northwest Area (street-level)	6/20/08	3.81	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	
SILICA-ST5-6/20/08	040815273-0004	Firehouse #10 (roof level)	6/20/08	3.5	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	
SILICA-ST10-6/20/08	040815273-0005	North Side Sidewalk Bridge	6/20/08	3.74	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	
SILICA-ST11-6/20/08	040815273-0006	90 Trinity Place (roof level)	6/20/08	3.53	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	
SILICA-ST12-6/20/08	040815273-0007	110 Greenwich Street (roof level)	6/20/08	3.52	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	
SILICA-ST13-6/20/08	040815273-0008	Marriott Hotel, 38th Floor (roof level)	6/20/08	3.63	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	
SILICA-ST14(15th) -6/20/08	040815273-0009	West Face - South end at corner (scaffolding level: 15th floor)	6/20/08	3.4	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	
SILICA-ST15(15th) -6/20/08	040815273-0010	South Face - East end at corner (scaffolding level: 15th floor)	6/20/08	3.38	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	
SILICA-ST16(15th) -6/20/08	040815273-0011	East Face - North end at corner (scaffolding level: 15th floor)	6/20/08	3.37	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	
SILICA-ST17(15th) -6/20/08	040815273-0012	North Face - West end at corner (scaffolding level: 15th floor)	6/20/08	3.31	Silica	NIOSH 7500 XRD	EMSL	6/21/08	< 1	No	No	