

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-6/25/08	040815865-0001	Southwest Area (sidewalk bridge level)	6/25/08	3.57	Silica	NIOSH 7500 XRD	EMSL	6/26/08	2	No	No	
SILICA-ST2-6/25/08	040815865-0002	Southeast Area (sidewalk bridge level)	6/25/08	3.62	Silica	NIOSH 7500 XRD	EMSL	6/26/08	< 1	No	No	
SILICA-ST4-6/25/08	040815865-0003	Northwest Area (street-level)	6/25/08	3.64	Silica	NIOSH 7500 XRD	EMSL	6/26/08	< 1	No	No	
SILICA-ST5-6/25/08	040815865-0004	Firehouse #10 (roof level)	6/25/08	3.61	Silica	NIOSH 7500 XRD	EMSL	6/26/08	1	No	No	
SILICA-ST10-6/25/08	040815865-0005	North Side Sidewalk Bridge	6/25/08	3.59	Silica	NIOSH 7500 XRD	EMSL	6/26/08	< 1	No	No	
SILICA-ST11-6/25/08	040815865-0006	90 Trinity Place (roof level)	6/25/08	3.49	Silica	NIOSH 7500 XRD	EMSL	6/26/08	< 1	No	No	
SILICA-ST12-6/25/08	040815865-0007	110 Greenwich Street (roof level)	6/25/08	3.68	Silica	NIOSH 7500 XRD	EMSL	6/26/08	< 1	No	No	
SILICA-ST14(15th) -6/25/08	040815865-0009	West Face - South end at corner (scaffolding level: 15th floor)	6/25/08	3.56	Silica	NIOSH 7500 XRD	EMSL	6/26/08	< 1	No	No	
SILICA-ST15(15th) -6/25/08	040815865-0010	South Face - East end at corner (scaffolding level: 15th floor)	6/25/08	3.6	Silica	NIOSH 7500 XRD	EMSL	6/26/08	< 1	No	No	
SILICA-ST16(15th) -6/25/08	040815865-0011	East Face - North end at corner (scaffolding level: 15th floor)	6/25/08	3.56	Silica	NIOSH 7500 XRD	EMSL	6/26/08	< 1	No	No	
SILICA-ST17(15th) -6/25/08	040815865-0012	North Face - West end at corner (scaffolding level: 15th floor)	6/25/08	3.59	Silica	NIOSH 7500 XRD	EMSL	6/26/08	< 1	No	No	
SILICA-ST1-6/26/08	040816024-0001	Southwest Area (sidewalk bridge level)	6/26/08	3.65	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	
SILICA-ST2-6/26/08	040816024-0002	Southeast Area (sidewalk bridge level)	6/26/08	3.58	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	
SILICA-ST4-6/26/08	040816024-0003	Northwest Area (street-level)	6/26/08	3.6	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	
SILICA-ST5-6/26/08	040816024-0004	Firehouse #10 (roof level)	6/26/08	3.6	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	
SILICA-ST10-6/26/08	040816024-0005	North Side Sidewalk Bridge	6/26/08	3.73	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	
SILICA-ST11-6/26/08	040816024-0006	90 Trinity Place (roof level)	6/26/08	3.6	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	
SILICA-ST12-6/26/08	040816024-0007	110 Greenwich Street (roof level)	6/26/08	3.51	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	
SILICA-ST13-6/26/08	040816024-0008	Marriott Hotel, 38th Floor (roof level)	6/26/08	3.48	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	
SILICA-ST14(15th) -6/26/08	040816024-0009	West Face - South end at corner (scaffolding level: 15th floor)	6/26/08	3.63	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	
SILICA-ST15(15th) -6/26/08	040816024-0010	South Face - East end at corner (scaffolding level: 15th floor)	6/26/08	3.63	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	
SILICA-ST16(15th) -6/26/08	040816024-0011	East Face - North end at corner (scaffolding level: 15th floor)	6/26/08	3.61	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	
SILICA-ST17(15th) -6/26/08	040816024-0012	North Face - West end at corner (scaffolding level: 15th floor)	6/26/08	3.53	Silica	NIOSH 7500 XRD	EMSL	6/27/08	< 1	No	No	

Note:

1. Silica sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on June 25, 2008 was not available for analysis on account of equipment malfunction.