

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									10			
SILICA-ST1-6/28/06	040613295-0001	Southwest Area (sidewalk bridge level)	6/28/06	3.63	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	
SILICA-ST2-6/28/06	040613295-0002	Southeast Area (sidewalk bridge level)	6/28/06	3.63	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	
SILICA-ST4-6/28/06	040613295-0003	Northwest Area (street-level)	6/28/06	3.61	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	
SILICA-ST5-6/28/06	040613295-0004	Firehouse #10 (roof level)	6/28/06	3.62	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	
SILICA-ST10-6/28/06	040613295-0005	North Side Sidewalk Bridge	6/28/06	3.58	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	
SILICA-ST11-6/28/06	040613295-0006	90 Trinity Place (roof level)	6/28/06	3.58	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	
SILICA-ST12-6/28/06	040613295-0007	110 Greenwich Street (roof level)	6/28/06	3.58	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	
SILICA-ST13-6/28/06	040613295-0008	Marriott Hotel, 38th Floor (roof level)	6/28/06	3.51	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	
SILICA-ST14-6/28/06	040613295-0009	West Face - South end at corner (scaffolding level)	6/28/06	3.6	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	
SILICA-ST15-6/28/06	040613295-0010	South Face - East end at corner (scaffolding level)	6/28/06	3.57	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	
SILICA-ST16-6/28/06	040613295-0011	East Face - North end at corner (scaffolding level)	6/28/06	3.51	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	
SILICA-ST17-6/28/06	040613295-0012	North Face - West end at corner (scaffolding level)	6/28/06	3.58	Silica	NIOSH 7500 XRD	EMSL	6/29/06	< 1	No	No	