

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
SILICA-ST1-9/1/09	040922093-0001	Southwest Area (sidewalk bridge level)	9/1/09	3.63	Silica	NIOSH 7500 XRD	EMSL	9/2/09	< 1	No	No	
SILICA-ST2-9/1/09	040922093-0002	Southeast Area (sidewalk bridge level)	9/1/09	3.58	Silica	NIOSH 7500 XRD	EMSL	9/2/09	< 1	No	No	
SILICA-ST4-9/1/09	040922093-0003	Northwest Area (street-level)	9/1/09	3.64	Silica	NIOSH 7500 XRD	EMSL	9/2/09	< 1	No	No	
SILICA-ST5-9/1/09	040922093-0004	Firehouse #10 (roof level)	9/1/09	3.56	Silica	NIOSH 7500 XRD	EMSL	9/2/09	< 1	No	No	
SILICA-ST10-9/1/09	040922093-0005	North Side Sidewalk Bridge	9/1/09	3.53	Silica	NIOSH 7500 XRD	EMSL	9/2/09	< 1	No	No	
SILICA-ST11-9/1/09	040922093-0006	90 Trinity Place (roof level)	9/1/09	3.56	Silica	NIOSH 7500 XRD	EMSL	9/2/09	< 1	No	No	
SILICA-ST12-9/1/09	040922093-0007	110 Greenwich Street (roof level)	9/1/09	3.57	Silica	NIOSH 7500 XRD	EMSL	9/2/09	< 1	No	No	
SILICA-ST13-9/1/09	040922093-0008	Marriott Hotel, 38th Floor (roof level)	9/1/09	3.62	Silica	NIOSH 7500 XRD	EMSL	9/2/09	< 1	No	No	
SILICA-ST1-9/2/09	040922257-0001	Southwest Area (sidewalk bridge level)	9/2/09	3.59	Silica	NIOSH 7500 XRD	EMSL	9/3/09	< 1	No	No	
SILICA-ST2-9/2/09	040922257-0002	Southeast Area (sidewalk bridge level)	9/2/09	3.6	Silica	NIOSH 7500 XRD	EMSL	9/3/09	1	No	No	
SILICA-ST4-9/2/09	040922257-0003	Northwest Area (street-level)	9/2/09	3.77	Silica	NIOSH 7500 XRD	EMSL	9/3/09	< 1	No	No	
SILICA-ST5-9/2/09	040922257-0004	Firehouse #10 (roof level)	9/2/09	3.55	Silica	NIOSH 7500 XRD	EMSL	9/3/09	< 1	No	No	
SILICA-ST10-9/2/09	040922257-0005	North Side Sidewalk Bridge	9/2/09	3.77	Silica	NIOSH 7500 XRD	EMSL	9/3/09	< 1	No	No	
SILICA-ST11-9/2/09	040922257-0006	90 Trinity Place (roof level)	9/2/09	3.63	Silica	NIOSH 7500 XRD	EMSL	9/3/09	< 1	No	No	
SILICA-ST12-9/2/09	040922257-0007	110 Greenwich Street (roof level)	9/2/09	3.68	Silica	NIOSH 7500 XRD	EMSL	9/3/09	< 1	No	No	
SILICA-ST13-9/2/09	040922257-0008	Marriott Hotel, 38th Floor (roof level)	9/2/09	3.65	Silica	NIOSH 7500 XRD	EMSL	9/3/09	< 1	No	No	
SILICA-ST1-9/3/09	040922344-0001	Southwest Area (sidewalk bridge level)	9/3/09	3.57	Silica	NIOSH 7500 XRD	EMSL	9/4/09	< 1	No	No	
SILICA-ST2-9/3/09	040922344-0002	Southeast Area (sidewalk bridge level)	9/3/09	3.57	Silica	NIOSH 7500 XRD	EMSL	9/4/09	< 1	No	No	
SILICA-ST4-9/3/09	040922344-0003	Northwest Area (street-level)	9/3/09	3.63	Silica	NIOSH 7500 XRD	EMSL	9/4/09	< 1	No	No	
SILICA-ST5-9/3/09	040922344-0004	Firehouse #10 (roof level)	9/3/09	3.6	Silica	NIOSH 7500 XRD	EMSL	9/4/09	< 1	No	No	
SILICA-ST10-9/3/09	040922344-0005	North Side Sidewalk Bridge	9/3/09	3.69	Silica	NIOSH 7500 XRD	EMSL	9/4/09	< 1	No	No	
SILICA-ST11-9/3/09	040922344-0006	90 Trinity Place (roof level)	9/3/09	3.58	Silica	NIOSH 7500 XRD	EMSL	9/4/09	< 1	No	No	
SILICA-ST12-9/3/09	040922344-0007	110 Greenwich Street (roof level)	9/3/09	3.55	Silica	NIOSH 7500 XRD	EMSL	9/4/09	< 1	No	No	
SILICA-ST13-9/3/09	040922344-0008	Marriott Hotel, 38th Floor (roof level)	9/3/09	3.66	Silica	NIOSH 7500 XRD	EMSL	9/4/09	2	No	No	