

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									<b>10</b>	<b>Air Quality Levels</b>	<b>Site Specific Trigger Levels</b>	
<b>EPA Site Specific Trigger Levels</b>									<b>10</b>			
SILICA-ST1-10/18/07	040726160-0001	Southwest Area (sidewalk bridge level)	10/18/07	3.54	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	
SILICA-ST2-10/18/07	040726160-0002	Southeast Area (sidewalk bridge level)	10/18/07	3.49	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	
SILICA-ST4-10/18/07	040726160-0003	Northwest Area (street-level)	10/18/07	3.65	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	
SILICA-ST5-10/18/07	040726160-0004	Firehouse #10 (roof level)	10/18/07	3.49	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	
SILICA-ST10-10/18/07	040726160-0005	North Side Sidewalk Bridge	10/18/07	3.58	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	
SILICA-ST11-10/18/07	040726160-0006	90 Trinity Place (roof level)	10/18/07	3.69	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	
SILICA-ST12-10/18/07	040726160-0007	110 Greenwich Street (roof level)	10/18/07	3.62	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	
SILICA-ST13-10/18/07	040726160-0008	Marriott Hotel, 38th Floor (roof level)	10/18/07	3.63	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	
SILICA-ST14(15th) -10/18/07	040726160-0009	West Face - South end at corner (scaffolding level: 15th floor)	10/18/07	3.61	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	
SILICA-ST15(15th) -10/18/07	040726160-0010	South Face - East end at corner (scaffolding level: 15th floor)	10/18/07	3.4	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	
SILICA-ST16(15th) -10/18/07	040726160-0011	East Face - North end at corner (scaffolding level: 15th floor)	10/18/07	3.55	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	
SILICA-ST17(15th) -10/18/07	040726160-0012	North Face - West end at corner (scaffolding level: 15th floor)	10/18/07	3.49	Silica	NIOSH 7500 XRD	EMSL	10/19/07	< 1	No	No	