

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
SILICA-ST1-10/30/06	040623285-0001	Southwest Area (sidewalk bridge level)	10/30/06	3.49	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 1	No	No	
SILICA-ST2-10/30/06	040623285-0002	Southeast Area (sidewalk bridge level)	10/30/06	3.29	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 2	No	No	
SILICA-ST4-10/30/06	040623285-0003	Northwest Area (street-level)	10/30/06	3.64	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 1	No	No	
SILICA-ST5-10/30/06	040623285-0004	Firehouse #10 (roof level)	10/30/06	3.54	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 1	No	No	
SILICA-ST10-10/30/06	040623285-0005	North Side Sidewalk Bridge	10/30/06	3.6	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 1	No	No	
SILICA-ST11-10/30/06	040623285-0006	90 Trinity Place (roof level)	10/30/06	3.59	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 1	No	No	
SILICA-ST12-10/30/06	040623285-0007	110 Greenwich Street (roof level)	10/30/06	3.46	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 1	No	No	
SILICA-ST13-10/30/06	040623285-0008	Marriott Hotel, 38th Floor (roof level)	10/30/06	3.31	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 2	No	No	
SILICA-ST14-10/30/06	040623285-0009	West Face - South end at corner (scaffolding level)	10/30/06	3.7	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 1	No	No	
SILICA-ST15-10/30/06	040623285-0010	South Face - East end at corner (scaffolding level)	10/30/06	3.44	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 1	No	No	
SILICA-ST16-10/30/06	040623285-0011	East Face - North end at corner (scaffolding level)	10/30/06	3.36	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 1	No	No	
SILICA-ST17-10/30/06	040623285-0012	North Face - West end at corner (scaffolding level)	10/30/06	3.81	Silica	NIOSH 7500 XRD	EMSL	10/31/06	< 1	No	No	