

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-11/6/07	040727808-0001	Southwest Area (sidewalk bridge level)	11/6/07	3.54	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST2-11/6/07	040727808-0002	Southeast Area (sidewalk bridge level)	11/6/07	3.64	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST4-11/6/07	040727808-0003	Northwest Area (street-level)	11/6/07	3.61	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST5-11/6/07	040727808-0004	Firehouse #10 (roof level)	11/6/07	3.72	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST10-11/6/07	040727808-0005	North Side Sidewalk Bridge	11/6/07	3.41	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST11-11/6/07	040727808-0006	90 Trinity Place (roof level)	11/6/07	3.52	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST12-11/6/07	040727808-0007	110 Greenwich Street (roof level)	11/6/07	3.59	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST13-11/6/07	040727808-0008	Marriott Hotel, 38th Floor (roof level)	11/6/07	3.59	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST14(15th) -11/6/07	040727808-0009	West Face - South end at corner (scaffolding level: 15th floor)	11/6/07	3.56	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST15(15th) -11/6/07	040727808-0010	South Face - East end at corner (scaffolding level: 15th floor)	11/6/07	3.45	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST16(15th) -11/6/07	040727808-0011	East Face - North end at corner (scaffolding level: 15th floor)	11/6/07	3.79	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST17(15th) -11/6/07	040727808-0012	North Face - West end at corner (scaffolding level: 15th floor)	11/6/07	3.57	Silica	NIOSH 7500 XRD	EMSL	11/7/07	< 1	No	No	
SILICA-ST1-11/7/07	040727937-0001	Southwest Area (sidewalk bridge level)	11/7/07	3.46	Silica	NIOSH 7500 XRD	EMSL	11/8/07	< 1	No	No	
SILICA-ST2-11/7/07	040727937-0002	Southeast Area (sidewalk bridge level)	11/7/07	3.58	Silica	NIOSH 7500 XRD	EMSL	11/8/07	< 1	No	No	
SILICA-ST4-11/7/07	040727937-0003	Northwest Area (street-level)	11/7/07	3.64	Silica	NIOSH 7500 XRD	EMSL	11/8/07	< 1	No	No	
SILICA-ST5-11/7/07	040727937-0004	Firehouse #10 (roof level)	11/7/07	3.62	Silica	NIOSH 7500 XRD	EMSL	11/8/07	< 1	No	No	
SILICA-ST10-11/7/07	040727937-0005	North Side Sidewalk Bridge	11/7/07	3.49	Silica	NIOSH 7500 XRD	EMSL	11/8/07	< 1	No	No	
SILICA-ST11-11/7/07	040727937-0006	90 Trinity Place (roof level)	11/7/07	3.56	Silica	NIOSH 7500 XRD	EMSL	11/8/07	< 1	No	No	
SILICA-ST13-11/7/07	040727937-0007	Marriott Hotel, 38th Floor (roof level)	11/7/07	3.57	Silica	NIOSH 7500 XRD	EMSL	11/8/07	< 1	No	No	
SILICA-ST14(15th) -11/7/07	040727937-0008	West Face - South end at corner (scaffolding level: 15th floor)	11/7/07	3.62	Silica	NIOSH 7500 XRD	EMSL	11/8/07	< 1	No	No	
SILICA-ST15(15th) -11/7/07	040727937-0009	South Face - East end at corner (scaffolding level: 15th floor)	11/7/07	3.58	Silica	NIOSH 7500 XRD	EMSL	11/8/07	< 1	No	No	
SILICA-ST16(15th) -11/7/07	040727937-0010	East Face - North end at corner (scaffolding level: 15th floor)	11/7/07	3.5	Silica	NIOSH 7500 XRD	EMSL	11/8/07	< 1	No	No	
SILICA-ST17(15th) -11/7/07	040727937-0011	North Face - West end at corner (scaffolding level: 15th floor)	11/7/07	3.56	Silica	NIOSH 7500 XRD	EMSL	11/8/07	< 1	No	No	

Note:

1. Silica sample at Station 12 (110 Greenwich Street [roof level]) on November 7, 2007 was not available for analysis on account of power failure.