

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
SILICA-ST1-11/15/06	040624548-0001	Southwest Area (sidewalk bridge level)	11/15/06	3.47	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	
SILICA-ST2-11/15/06	040624548-0002	Southeast Area (sidewalk bridge level)	11/15/06	3.59	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	
SILICA-ST4-11/15/06	040624548-0003	Northwest Area (street-level)	11/15/06	3.8	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	
SILICA-ST5-11/15/06	040624548-0004	Firehouse #10 (roof level)	11/15/06	3.57	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	
SILICA-ST10-11/15/06	040624548-0005	North Side Sidewalk Bridge	11/15/06	3.41	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	
SILICA-ST11-11/15/06	040624548-0006	90 Trinity Place (roof level)	11/15/06	3.56	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	
SILICA-ST12-11/15/06	040624548-0007	110 Greenwich Street (roof level)	11/15/06	3.53	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	
SILICA-ST13-11/15/06	040624548-0008	Marriott Hotel, 38th Floor (roof level)	11/15/06	3.71	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	
SILICA-ST14-11/15/06	040624548-0009	West Face - South end at corner (scaffolding level)	11/15/06	3.66	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	
SILICA-ST15-11/15/06	040624548-0010	South Face - East end at corner (scaffolding level)	11/15/06	3.62	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	
SILICA-ST16-11/15/06	040624548-0011	East Face - North end at corner (scaffolding level)	11/15/06	3.52	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	
SILICA-ST17-11/15/06	040624548-0012	North Face - West end at corner (scaffolding level)	11/15/06	3.6	Silica	NIOSH 7500 XRD	EMSL	11/16/06	< 1	No	No	