

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									<b>10</b>	<b>Exceeds Target Air Quality Levels</b>	<b>Exceeds EPA Site Specific Trigger Levels</b>	
<b>EPA Site Specific Trigger Levels</b>									<b>10</b>			
SILICA-ST1-11/23/09	040928562-0001	Southwest Area (sidewalk bridge level)	11/23/09	3.69	Silica	NIOSH 7500 XRD	EMSL	11/25/09	< 1	No	No	
SILICA-ST2-11/23/09	040928562-0002	Southeast Area (sidewalk bridge level)	11/23/09	3.73	Silica	NIOSH 7500 XRD	EMSL	11/25/09	< 1	No	No	
SILICA-ST4-11/23/09	040928562-0003	Northwest Area (street-level)	11/23/09	3.63	Silica	NIOSH 7500 XRD	EMSL	11/25/09	< 1	No	No	
SILICA-ST5-11/23/09	040928562-0004	Firehouse #10 (roof level)	11/23/09	3.62	Silica	NIOSH 7500 XRD	EMSL	11/25/09	< 1	No	No	
SILICA-ST10-11/23/09	040928562-0005	North Side Sidewalk Bridge	11/23/09	3.64	Silica	NIOSH 7500 XRD	EMSL	11/25/09	< 1	No	No	
SILICA-ST11-11/23/09	040928562-0006	90 Trinity Place (roof level)	11/23/09	3.54	Silica	NIOSH 7500 XRD	EMSL	11/25/09	< 1	No	No	
SILICA-ST12-11/23/09	040928562-0007	110 Greenwich Street (roof level)	11/23/09	3.75	Silica	NIOSH 7500 XRD	EMSL	11/25/09	< 1	No	No	
SILICA-ST13-11/23/09	040928562-0008	Marriott Hotel, 38th Floor (roof level)	11/23/09	3.46	Silica	NIOSH 7500 XRD	EMSL	11/25/09	< 1	No	No	
SILICA-ST1-11/24/09	040928745-0001	Southwest Area (sidewalk bridge level)	11/24/09	3.64	Silica	NIOSH 7500 XRD	EMSL	11/27/09	< 1	No	No	
SILICA-ST2-11/24/09	040928745-0002	Southeast Area (sidewalk bridge level)	11/24/09	3.69	Silica	NIOSH 7500 XRD	EMSL	11/27/09	< 1	No	No	
SILICA-ST4-11/24/09	040928745-0003	Northwest Area (street-level)	11/24/09	3.54	Silica	NIOSH 7500 XRD	EMSL	11/27/09	< 1	No	No	
SILICA-ST5-11/24/09	040928745-0004	Firehouse #10 (roof level)	11/24/09	3.59	Silica	NIOSH 7500 XRD	EMSL	11/27/09	< 1	No	No	
SILICA-ST10-11/24/09	040928745-0005	North Side Sidewalk Bridge	11/24/09	3.64	Silica	NIOSH 7500 XRD	EMSL	11/27/09	< 1	No	No	
SILICA-ST100-11/24/09	040928745-0009	Station 10 Field Duplicate	11/24/09	3.66	Silica	NIOSH 7500 XRD	EMSL	11/27/09	< 1	No	No	
SILICA-ST11-11/24/09	040928745-0006	90 Trinity Place (roof level)	11/24/09	3.61	Silica	NIOSH 7500 XRD	EMSL	11/27/09	< 1	No	No	
SILICA-ST12-11/24/09	040928745-0007	110 Greenwich Street (roof level)	11/24/09	3.49	Silica	NIOSH 7500 XRD	EMSL	11/27/09	< 1	No	No	
SILICA-ST13-11/24/09	040928745-0008	Marriott Hotel, 38th Floor (roof level)	11/24/09	3.64	Silica	NIOSH 7500 XRD	EMSL	11/27/09	< 1	No	No	

Note:

1. Silica results are not available for November 22, 2009 since no sampling was conducted on this day due to the lack of work activities. This is in accordance with Amendment #9 to the September 2005 Ambient Air Monitoring Program Plan.