

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Air Quality Levels	Site Specific Trigger Levels	
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
SILICA-ST1-11/24/10	041027490-0001	Southwest Area (sidewalk bridge level)	11/24/10	3.76	Silica	NIOSH 7500 XRD	EMSL	11/29/10	< 1	No	No	
SILICA-ST2-11/24/10	041027490-0002	Southeast Area (sidewalk bridge level)	11/24/10	3.65	Silica	NIOSH 7500 XRD	EMSL	11/29/10	< 1	No	No	
SILICA-ST4-11/24/10	041027490-0003	Northwest Area (street-level)	11/24/10	3.65	Silica	NIOSH 7500 XRD	EMSL	11/29/10	< 1	No	No	
SILICA-ST20-11/24/10	041027490-0004	Northeast Area, Sidewalk Bridge	11/24/10	3.56	Silica	NIOSH 7500 XRD	EMSL	11/29/10	< 1	No	No	
SILICA-ST200-11/24/10	041027490-0005	Station 20 Field Duplicate	11/24/10	3.68	Silica	NIOSH 7500 XRD	EMSL	11/29/10	< 1	No	No	
SILICA-ST1-11/29/10	041027662-0001	Southwest Area (sidewalk bridge level)	11/29/10	3.59	Silica	NIOSH 7500 XRD	EMSL	12/1/10	< 1	No	No	
SILICA-ST2-11/29/10	041027662-0002	Southeast Area (sidewalk bridge level)	11/29/10	3.61	Silica	NIOSH 7500 XRD	EMSL	12/1/10	< 1	No	No	
SILICA-ST4-11/29/10	041027662-0003	Northwest Area (street-level)	11/29/10	3.64	Silica	NIOSH 7500 XRD	EMSL	12/1/10	4	No	No	
SILICA-ST20-11/29/10	041027662-0004	Northeast Area, Sidewalk Bridge	11/29/10	3.66	Silica	NIOSH 7500 XRD	EMSL	12/1/10	< 1	No	No	

Note:

- The silica results are not available for November 25, 26, 27, and 28, 2010 since no sampling was conducted on these days due to the lack of work activities. This is in accordance with Amendment #9 to the September 2005 Ambient Air Monitoring Program Plan.