

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									10			
SILICA-ST1-11/25/09	040928889-0001	Southwest Area (sidewalk bridge level)	11/25/09	3.66	Silica	NIOSH 7500 XRD	EMSL	12/1/09	< 1	No	No	
SILICA-ST2-11/25/09	040928889-0002	Southeast Area (sidewalk bridge level)	11/25/09	3.51	Silica	NIOSH 7500 XRD	EMSL	12/1/09	< 1	No	No	
SILICA-ST4-11/25/09	040928889-0003	Northwest Area (street-level)	11/25/09	3.67	Silica	NIOSH 7500 XRD	EMSL	12/1/09	< 1	No	No	
SILICA-ST5-11/25/09	040928889-0004	Firehouse #10 (roof level)	11/25/09	3.64	Silica	NIOSH 7500 XRD	EMSL	12/1/09	< 1	No	No	
SILICA-ST10-11/25/09	040928889-0005	North Side Sidewalk Bridge	11/25/09	3.63	Silica	NIOSH 7500 XRD	EMSL	12/1/09	< 1	No	No	
SILICA-ST11-11/25/09	040928889-0006	90 Trinity Place (roof level)	11/25/09	3.46	Silica	NIOSH 7500 XRD	EMSL	12/1/09	< 1	No	No	
SILICA-ST12-11/25/09	040928889-0007	110 Greenwich Street (roof level)	11/25/09	3.69	Silica	NIOSH 7500 XRD	EMSL	12/1/09	< 1	No	No	
SILICA-ST13-11/25/09	040928889-0008	Marriott Hotel, 38th Floor (roof level)	11/25/09	3.66	Silica	NIOSH 7500 XRD	EMSL	12/1/09	< 1	No	No	