

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-12/15/06	040626672-0001	Southwest Area (sidewalk bridge level)	12/15/06	3.45	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST2-12/15/06	040626672-0002	Southeast Area (sidewalk bridge level)	12/15/06	3.46	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST4-12/15/06	040626672-0003	Northwest Area (street-level)	12/15/06	3.48	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST5-12/15/06	040626672-0004	Firehouse #10 (roof level)	12/15/06	3.47	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST10-12/15/06	040626672-0005	North Side Sidewalk Bridge	12/15/06	3.49	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST11-12/15/06	040626672-0006	90 Trinity Place (roof level)	12/15/06	3.65	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST12-12/15/06	040626672-0007	110 Greenwich Street (roof level)	12/15/06	3.54	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST13-12/15/06	040626672-0008	Marriott Hotel, 38th Floor (roof level)	12/15/06	3.21	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 2	No	No	
SILICA-ST14-12/15/06	040626672-0009	West Face - South end at corner (scaffolding level)	12/15/06	3.1	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 2	No	No	
SILICA-ST15-12/15/06	040626672-0010	South Face - East end at corner (scaffolding level)	12/15/06	3.16	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 2	No	No	
SILICA-ST16-12/15/06	040626672-0011	East Face - North end at corner (scaffolding level)	12/15/06	3.17	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 2	No	No	
SILICA-ST17-12/15/06	040626672-0012	North Face - West end at corner (scaffolding level)	12/15/06	3.17	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 2	No	No	
SILICA-ST1-12/16/06	040626674-0001	Southwest Area (sidewalk bridge level)	12/16/06	3.55	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST2-12/16/06	040626674-0002	Southeast Area (sidewalk bridge level)	12/16/06	3.54	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST4-12/16/06	040626674-0003	Northwest Area (street-level)	12/16/06	3.64	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST5-12/16/06	040626674-0004	Firehouse #10 (roof level)	12/16/06	3.64	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST10-12/16/06	040626674-0005	North Side Sidewalk Bridge	12/16/06	3.61	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST11-12/16/06	040626674-0006	90 Trinity Place (roof level)	12/16/06	3.51	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST12-12/16/06	040626674-0007	110 Greenwich Street (roof level)	12/16/06	3.53	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST14-12/16/06	040626674-0008	West Face - South end at corner (scaffolding level)	12/16/06	3.53	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST15-12/16/06	040626674-0009	South Face - East end at corner (scaffolding level)	12/16/06	3.61	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST16-12/16/06	040626674-0010	East Face - North end at corner (scaffolding level)	12/16/06	3.6	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	
SILICA-ST17-12/16/06	040626674-0011	North Face - West end at corner (scaffolding level)	12/16/06	3.54	Silica	NIOSH 7500 XRD	EMSL	12/18/06	< 1	No	No	

Note:

1. Silica sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on December 16, 2006 was not available for analysis on account of power failure.